

## Light Outage Reporting

<https://oeaaa.faa.gov/oeaaa/external/content/lightOutageReporting.jsp>

Sponsors should keep in mind that conspicuity is achieved only when all recommended lights are working. Partial equipment outages decrease the margin of safety. Any outage should be corrected as soon as possible. Failure of a steady burning side or intermediate light should be corrected as soon as possible, but notification is not required.

**Any failure or malfunction that lasts more than thirty (30) minutes and affects a top light or flashing obstruction light, regardless of its position, should be reported immediately by calling 877-487-6867 so a Notice to Airmen (NOTAM) can be issued.**

When reporting, please have available:

1. Name of persons or organizations reporting light failures, including any title, address and phone number
2. The type of Structure
3. Location of structure (including latitude/longitude, if known, prominent structures, landmarks, etc...)
4. Height of structure above ground level (AGL)/above mean sea level (AMSL), if known  
\*\*Circle Search may be used to obtain information for items 3. and 4.\*\*
5. A return to service date
6. FCC Antenna Registration Number (for structures that are regulated by the FCC)  
\*\*The FCC advises that noncompliance with notification procedures could subject its sponsor to penalties or monetary forfeitures\*\*

**As soon as normal operation is restored, please call 877-487-6867. After 15 days, the NOTAM is automatically deleted from the system. The sponsor is responsible for calling 877-487-6867 to extend the outage date or to report a return to service date.**

Advisory Circular 70/7460-1K, Obstruction Marking and lighting, describes the standards for marking and lighting structures such as buildings, chimneys, antenna towers, cooling towers, storage tanks, supporting structures of overhead wires, etc...